

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

CAPU

Applicant: Sungkwon Hong et al.

Examiner: Stephen K Yam

Patent No.: 7,253,392

Group Art Unit: 2878

Issue Date: August 7, 2007

Docket No: 2002-1376.00/US

Title: IMAGE SENSOR WITH PHOTO DIODE GATE

ATTN: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Certificate of Correction

We are transmitting herewith the attached:

Request for Certificate of Correction.

Certificate of Correction Form - PTO-1050 (in duplicate)

A return postcard.

Please charge any additional fees or credit overpayment to Deposit Account No. 13-3092.

Customer Number: 26809

Respectfully submitted,

Date: September 10, 2007

Russ Slifer

Reg. No. 39,838

CERTIFICATE UNDER 37 CFR 1.8: The undersigned hereby certifies that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail, in an envelope addressed to: ATTN: Certificate of Correction Branch, Commissioner of Patents and Trademarks, P.O. Box 1450, Alexandria VA 22313-1450, on this ____ day of September 2007.

SEP 17 2007

IN UNITED STATES PAPTENT AND TRADEMARK OFFICE

Patent No.: 7,253,392

Issue Date: August 7, 2007

SEP 1 3 2007

Docket No: 2002-1376.00/US Patentee: Sungkwon Hong et al.

Title: IMAGE SENSOR WITH PH

TO DIODE ATE

REQUEST FOR CERTIFICATION OF CORRECTION

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

ATTN: Certificate of Correction Branch

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. Two copies of the text of the Certificate in the suggested form are enclosed.

As the error is that of the Patent Office, it is believed that no fee is due.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

Respectfully submitted,

Customer Number: 26809

Date: September 10, 2007

Russ Slifer

Reg. No. 39,838

Name

Signature

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 7,253,392

Page (1) of 1

DATED

: August 7, 2007

INVENTOR(S)

: Hong et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (54), in column 1, line 1, before "IMAGE" insert - - CMOS - -.

In column 1, line 1, before "IMAGE" insert - - CMOS - -.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 7,253,392

Page (1) of 1

DATED

: August 7, 2007

INVENTOR(S)

: Hong et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (54), in column 1, line 1, before "IMAGE" insert - - CMOS - -.

In column 1, line 1, before "IMAGE" insert - - CMOS - -.

SEP 17 2007.